50639

LUBRIZOL

LUBRIZOL PETROLEUM CHEMICALS COMPANY P.O. BOX 158
41 TIDAL ROAD
DEER PARK, TX 77536-0158
TELEPHONE: 713/479-2851

NWM-082-92

November 6, 1992

Texas Water Commission Self-Reporting Section P.O. Box 13087, Capitol Station Austin, Texas 78711-3087

RE: Permit No. WQ000639

Please be informed that a recent <u>water discharge from Lubrizol</u> Petroleum Chemicals Company - Deer Park Plant <u>exceeded limits</u> of the referenced permit as follows:

<u>Date</u>	Outfall Outfall	<u>Parameter</u>	Result	<u>Limit</u>
11/01/92	002	pH, Std. Units	9.4	6.9-9.0 Max

Due to extensive rainfall in the area of outfall 002, Lubrizol believes that stabilization and construction associated with the Outfall 002 stormwater retention system contributed to an elevated pH value at 9.4 std. units on 11/01/92 (6.0-9.0 max.).

If you have any questions, please contact me at 713/479-2851, extension 300.

Truly yours,

LUBRIZOL PETROLEUM CHEMICALS CO.

Cecil A. Scott

Works Manager, Deer Park Plant

CAS/nwm

9155424

